

Professional Documentation

The Attached Report is performed by OnSight PROS, LLC Certified Field Inspectors and thus should not be confused with an inspection performed by Licensed Real Estate Commission Inspectors. This report is an assessment of the condition of the property on the date shown and only the items listed in the report with notations made are reported on. Certified Field Inspectors are not licensed to check the mechanicals, plumbing, or electrical units in a home and therefore this report will not reflect any issues or functionality of those components. This report is for the use of the property manager and/or owner to see first hand the condition of the property address as shown on the report. If no safety issues or deficiencies are observed, NO COMMENTS will be made.



INSPECTION DATE	TECHNICIAN	INSPECTION TYPE
6/9/2016	Keith Mitchell	Periodic
PROPERTY LOCATION	PROPERTY I	MANAGER

SERVICES PERFORMED

ITEM LOCATION

Basic Property Report

NOTES

SMELL TEST

Smell Test Performed. No exceptions noted.

SUMMARY OF ITEMS THAT NEED FURTHER EVALUATION

Front Exterior



Front Exterior Landscaping
Tree not trimmed.

Rear Exterior



Rear Exterior Fence Broken slat.



Rear Exterior
Fence
Section detached from fence post.

END OF SUMMARY OF ITEMS THAT NEED FURTHER EVALUATION

Front Exterior Observed Not Applicable Attention Needed

PROPERTY DETAIL

Front Exterior			Observed	Not Applicable	Attention Needed
1 . Street Overview					
2. Address					
3 . Front Left View					
4 . Center View					
5 . Front Right View					
6 . Driveway					
7. Garage Door					
8 . Sidewalks					
9. Yard					
10 . Landscaping					×
11 . Roof/Trim					
12 . Walls/Siding/Trim					
13 . Window Screens					
14 . Light Fixtures					
1	6/9/2016 3:13 PM	2		(6/9/2016 3:13 PM



Street Overview



Front Exterior Observed Not Applicable Attention Needed

3 6/9/2016 3:13 PM



Front Left View

5 6/9/2016 3:13 PM



Front Right View

7 6/9/2016 3:14 PM



Garage Door

4 6/9/2016 3:13 PM



Center View

6 6/9/2016 3:14 PM



Driveway

8 6/9/2016 3:14 PM



Sidewalks

Front Exterior Observed Not Applicable Attention Needed

9 6/9/2016 3:14 PM



Yard

10 6/9/2016 3:22 PM




Landscaping - Tree not trimmed.

12 6/9/2016 3:14 PM



Walls/Siding/Trim

10 6/9/2016 3:14 PM



Landscaping

11 6/9/2016 3:14 PM



Roof/Trim

13 6/9/2016 3:14 PM



Window Screens

Light Fixtures

Front Exterior Observed Not Applicable Attention Needed

14 6/9/2016 3:15 PM 14 6/9/2016 3:15 PM







Light Fixtures

Rear Exterior	Observed	Not Applicable	Attention Needed
1 . Rear Gate			
2. Overview			
3 . Roof/Trim			
4. Walls/Siding/Trim			
5. Window Screens			
6. Yard			
7. Landscaping			
8 . Patio/Porch			
9. BBQ Grill			
10 . Rear Door			
11 . Keyless Deadbolt			
12. Peephole			
13 . Fence			×
14 . Pet Evidence		N/A	
15 . Light Fixtures			

Rear Exterior Observed Not Applicable Attention Needed

6/9/2016 3:15 PM 1



Rear Gate

6/9/2016 3:16 PM 2



Overview

6/9/2016 3:17 PM 4



Walls/Siding/Trim

2

6/9/2016 3:16 PM



Overview

6/9/2016 3:16 PM



Roof/Trim

6/9/2016 3:17 PM 5



Window Screens

Rear Exterior Observed Not Applicable Attention Needed

6/9/2016 3:18 PM 6



Yard

6/9/2016 3:18 PM 8



Patio/Porch

6/9/2016 3:18 PM 10



Rear Door

7

6/9/2016 3:18 PM



Landscaping

6/9/2016 3:18 PM 9



BBQ Grill

6/9/2016 3:25 PM 11



Keyless Deadbolt

Rear Exterior Observed Not Applicable Attention Needed

12 6/9/2016 3:18 PM



Peephole

13 6/9/2016 3:20 PM



Fence

13 6/9/2016 3:20 PM



Fence

13 6/9/2016 3:20 PM



Fence

13 6/9/2016 3:20 PM



Fence

13 6/9/2016 3:20 PM



Fence - Broken slat.

Rear Exterior Observed Not Applicable Attention Needed

13 6/9/2016 3:20 PM **15**



Fence - Section detached from fence post.

15 6/9/2016 3:21 PM



Light Fixtures



6/9/2016 3:21 PM

Light Fixtures

Entry	Observed	Not Applicable	Attention Needed
1 . Porch/Patio			
2 . Front Door Exterior			
3. Overview (Interior)			
4. Front Door Interior			
5. Keyless Lock/Deadbolt*			
6. Peephole*			
7. Floors			
8 . Ceiling			

Entry

- 9. Walls/Paint
- 10 . Door Stops
- 11. Outlet/Switch Covers
- 12 . Light Fixtures
- 13 . Smoke Alarm

SMOKE ALARM TEST: Pass ALARM TYPE: Wired

MANUFACTURE DATE: June 2008

1 6/9/2016 3:15 PM



Porch/Patio

3 6/9/2016 3:26 PM



Overview (Interior)



Not Applicable

Attention Needed



















6/9/2016 3:15 PM



Front Door Exterior

2


4 6/9/2016 3:26 PM



Front Door Interior

Observed Not Applicable Attention Needed Entry

6/9/2016 3:26 PM 5



Keyless Lock/Deadbolt*

6/9/2016 3:26 PM 7




Floors

6/9/2016 3:27 PM 9



Walls/Paint

6/9/2016 3:26 PM



Peephole*

6/9/2016 3:26 PM 8



Ceiling

6/9/2016 3:28 PM 13



Smoke Alarm

OnSight PROS Report Living Room Observed Not Applicable Attention Needed 1 . Overview 2 . Flooring 3 . Ceiling 4 . Walls/Paint 5 . Windows 6 . Blinds/Drapes 7 . Outlet/Switch Covers

9. Ceiling Fan

8 . Light Fixture

10 . Smoke Alarm

SMOKE ALARM TEST: Pass


ALARM TYPE: Wired

MANUFACTURE DATE: June 2008

1 6/9/2016 3:29 PM **2** 6/9/2016 3:29 PM



Overview Flooring




Living Room Observed Not Applicable Attention Needed

3 6/9/2016 3:29 PM



Ceiling

10 6/9/2016 3:31 PM



Smoke Alarm



Dining Room	Observed	Not Applicable	Attention Needed
1. Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			

Dining Room

1

Observed


Not Applicable

Attention Needed

- 9. Light Fixture
- 10 . Smoke Alarm

6/9/2016 3:32 PM

6/9/2016 3:32 PM



Overview

6/9/2016 3:32 PM 3



Flooring

2

6/9/2016 3:32 PM 4





Kitchen Observed Not Applicable Attention Needed 1. Overview

- 2. Flooring
- 3. Ceiling
- 4. Walls/Paint
- 5. Sink/Faucet
- 6. Cabinet Under Sink

_			

ſ	
ŀ	
ı	


Г		

Page 15

Observed Not Applicable Attention Needed Kitchen 7. Garbage Disposal 8. Range/Cooktop/Oven 9. Microwave Oven 10 . Dishwasher 11. Refrigerator 12. Lower Cabinets 13. Counter Top/Back Splash 14. Upper Cabinets 15 . Pantry 16. Outlet/Switch Covers 17 . Light Fixture 18 . Smoke Alarm

6/9/2016 3:32 PM 6/9/2016 3:33 PM 2 1





Overview Flooring Kitchen Observed Not Applicable Attention Needed

3 6/9/2016 3:33 PM



Ceiling

5 6/9/2016 3:33 PM




Sink/Faucet

7 6/9/2016 3:33 PM



Garbage Disposal



Walls/Paint

6 6/9/2016 3:33 PM



Cabinet Under Sink

8 6/9/2016 3:33 PM



Range/Cooktop/Oven

Kitchen Observed Not Applicable Attention Needed

9 6/9/2016 3:34 PM



Microwave Oven

11 6/9/2016 3:34 PM



Refrigerator



Dishwasher

Garage	Observed	Not Applicable	Attention Needed
1 . Passage Door Keyless Locks/Deadbolt			
2. Passage Door Peephole			
3. Overview			
4. Flooring			
5. Ceiling			
6. Walls/Paint			
7. Garage Door			
8. Garage Door Sliding Locks			

Garage

9. Garage Door Electric Opener

10 . Outlet/Switch Covers

11. Light Fixture

12 . Smoke Alarm

1 6/9/2016 3:35 PM



Passage Door Keyless Locks/Deadbolt

3 6/9/2016 3:38 PM



Overview









2 6/9/2016 3:35 PM



Passage Door Peephole


4 6/9/2016 3:38 PM



Flooring

Garage Observed Not Applicable Attention Needed

5 6/9/2016 3:38 PM



Ceiling

7 6/9/2016 3:38 PM



Garage Door

9 6/9/2016 3:39 PM



Garage Door Electric Opener



Walls/Paint

8 6/9/2016 3:39 PM



Garage Door Sliding Locks

Hallway/Stairway Observed Not Applicable

Hallway/Stairway

- 1. Overview
- 2. Flooring
- 3. Ceiling
- 4. Walls/Paint
- 5. Outlet/Switch Covers
- 6. Light Fixture
- 7. Smoke Alarm

SMOKE ALARM TEST: Pass ALARM TYPE: Wired

MANUFACTURE DATE: June 2008

6/9/2016 3:54 PM

6/9/2016 3:54 PM 2

Not Applicable

Attention Needed

Observed



Overview

1

3 6/9/2016 3:54 PM



4 6/9/2016 3:54 PM




Ceiling



Walls/Paint

Hallway/Stairway Observed Not Applicable Attention Needed

7 6/9/2016 3:56 PM



Smoke Alarm

Bathroom 2	Observed	Not Applicable	Attention Needed
1 . Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Sink/Faucet			
6. Cabinet Under Sink			
7. Commode			
8 . Tub/Fixture			
9 . Shower/Fixture			
10 . Door Stops			
11 . Towel Bars			
12 . Window			
13 . Outlet/Switch Covers			
14 . Light Fixtures			
15 . Exhaust Fan			
16 . Smoke Alarm		N/A	

Bathroom 2 Observed Not Applicable Attention Needed

2

1 6/9/2016 3:41 PM



Overview

3 6/9/2016 3:41 PM



Ceiling

5 6/9/2016 3:41 PM



Sink/Faucet

6/9/2016 3:41 PM



Flooring

4 6/9/2016 3:41 PM



Walls/Paint

6 6/9/2016 3:41 PM



Cabinet Under Sink

Bathroom 2 Observed Not Applicable Attention Needed

6/9/2016 3:42 PM 7




Commode

6/9/2016 3:42 PM 9



Shower/Fixture



6/9/2016 3:42 PM

Tub/Fixture

Bedroom 2	Observed	Not Applicable	Attention Needed	
1 . Overview				
2. Flooring				
3. Ceiling				
4. Walls/Paint				
5 . Door Stops				
6. Windows				
7. Blinds/Drapes				
8 Outlet/Switch Covers				

Bedroom 2

- 9. Light Fixture
- 10. Ceiling Fan
- 11. Closets
- 12 . Smoke Alarm

SMOKE ALARM TEST: Pass

ALARM TYPE: Wired


MANUFACTURE DATE: June 2008

1 6/9/2016 3:43 PM



Observed

Not Applicable




Attention Needed



Overview

3 6/9/2016 3:43 PM



Flooring

4 6/9/2016 3:43 PM



Ceiling



Walls/Paint

Bedroom 2 Observed Not Applicable Attention Needed

12 6/9/2016 3:45 PM



MANUFACTURE DATE: June 2008

Smoke Alarm

Bedroom 3	Observed	Not Applicable	Attention Needed
1 . Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			
9 . Light Fixture			
10 . Ceiling Fan			
11 . Closets			
12 . Smoke Alarm SMOKE ALARM TEST: Pass			


Observed Not Applicable Attention Needed Bedroom 3

6/9/2016 3:59 PM



Overview

6/9/2016 3:59 PM 3



Ceiling

6/9/2016 4:00 PM 12



Smoke Alarm

2 6/9/2016 3:59 PM



Flooring

6/9/2016 3:59 PM 4



Walls/Paint

Bedroom Master Observed Not Applicable Attention Needed


Observed Not Applicable **Bedroom Master** Attention Needed 1. Overview 2. Flooring 3. Ceiling 4. Walls/Paint 5. Door Stops 6. Windows 7. Blinds/Drapes 8. Outlet/Switch Covers 9. Light Fixture 10. Ceiling Fan 11. Smoke Alarm SMOKE ALARM TEST: Pass ALARM TYPE: Wired

1 6/9/2016 3:46 PM **2** 6/9/2016 3:46 PM



MANUFACTURE DATE: June 2008

Overview Flooring



Bedroom Master Observed Not Applicable Attention Needed

3 6/9/2016 3:46 PM **4** 6/9/2016 3:46 PM



Ceiling

11 6/9/2016 3:47 PM



Smoke Alarm



SHORE ALUM				
Bathroom Master	Observed	Not Applicable	Attention Needed	
1 . Overview				
2 . Flooring				
3. Ceiling				
4. Walls/Paint				
5 . Sink/Faucet				
6 . Cabinet Under Sink				
7. Commode				
8 . Tub/Fixture				

Bathroom Master

- 9. Shower/Fixture
- 10. Door Stops
- 11. Towel Bars
- 12. Window
- 13. Outlet/Switch Covers
- 14. Light Fixtures
- 15. Exhaust Fan
- 16. Smoke Alarm

6/9/2016 3:48 PM **2** 6/9/2016 3:48 PM

Observed

Not Applicable

Attention Needed



Overview

1

3 6/9/2016 3:48 PM **4**




Ceiling



Flooring

4 6/9/2016 3:48 PM



Walls/Paint

Bathroom Master Observed Not Applicable Attention Needed

6

5 6/9/2016 3:48 PM



Sink/Faucet

6 6/9/2016 3:49 PM



Cabinet Under Sink

8 6/9/2016 3:49 PM



Tub/Fixture

6/9/2016 3:48 PM



Cabinet Under Sink


7

6/9/2016 3:49 PM



Commode


8 6/9/2016 3:49 PM



Tub/Fixture

Bathroom Master Observed Not Applicable Attention Needed

9 6/9/2016 3:49 PM



Shower/Fixture

Utility Room	Observed	Not Applicable	Attention Needed
1 . Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5. Washer Connection			
6. Washing Machine			
7. Dryer			
8 . Door Stops			
9. Outlet/Switch Covers			
10 . Light Fixtures			
11 . Smoke Alarm		N/A	

Utility Room Observed Not Applicable Attention Needed

1 6/9/2016 3:53 PM



Overview

3 6/9/2016 3:53 PM



Ceiling

5 6/9/2016 3:53 PM



Washer Connection

2

6/9/2016 3:53 PM



Flooring

4

6/9/2016 3:53 PM



Walls/Paint

6

6/9/2016 3:53 PM



Washing Machine

 Utility Room
 Observed
 Not Applicable
 Attention Needed

7 6/9/2016 3:54 PM



Dryer

Miscellaneous	Observed	Not Applicable	Attention Needed
1 . Air Conditioner			
2. Thermostat			
3 . Security System			
4. Water Heater TYPE: Electric MANUFACTURER: AO Smith			
5 . AC Filter FILTER CONDITION: Filter recently replaced. Slightly dusty. FILTER SIZE: 20x25x1			
6 . AC Filter 2 FILTER CONDITION: Filter recently replaced. Slightly dusty. FILTER SIZE: 12x24x1			

Miscellaneous Observed Not Applicable Attention Needed

1 6/9/2016 3:17 PM



Air Conditioner

3 6/9/2016 3:55 PM



Security System

5 6/9/2016 4:02 PM



AC Filter - FILTER CONDITION: Filter recently replaced. Slightly dusty.

2

6/9/2016 3:52 PM



Thermostat

4 6/9/2016 3:39 PM



Water Heater

5 6/9/2016 4:03 PM



AC Filter

Miscellaneous Observed Not Applicable Attention Needed

6 6/9/2016 3:51 PM **6** 6/9/2016 3:51 PM



AC Filter 2 - FILTER CONDITION: Filter recently replaced. Slightly dusty.



AC Filter 2

Office	Observed	Not Applicable	Attention Needed
1. Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			
9 . Light Fixture			
10 . Smoke Alarm		N/A	

Office Observed Not Applicable Attention Needed


1 6/9/2016 3:58 PM




Overview

Flooring

2 6/9/2016 3:58 PM





Overview

3 6/9/2016 3:58 PM



Ceiling

END OF PROPERTY DETAIL

End of Report